

MATERIALS EVALUATED

1. Draft evaluation report for Canyon stone, Inc. Manufactured Stone & Brick Veneer, prepared by DeVit Consulting, Inc., undated.
2. Report of tests in accordance with the ICC ES Acceptance Criteria for Precast Stone Veneer (AC51), dated March 1, 2008, from RADCO – Test Report No. RAD-4837, dated November 24, 2010, for Canyon Stone Inc.
3. Completed and signed Appendix A of AC10, dated October 21, 2010, and completed and signed Appendix B of AC10, dated October 21, 2010.
4. Quality Control Manual for Manufactured Stone Veneer & Manufactured Brick Veneer, dated March 2010.
5. Completed Form Q20 for manufacturing facility in Olathe, Kansas, completed by Quality Control Consultants, LLC.
6. Completed Form Q20 for manufacturing facility in Wake Forest, North Carolina, completed by Quality Control Consultants, LLC.
7. Qualifying Inspection Report, Form Q21, dated November 17, 2010 for the manufacturing facility in Olathe, Kansas, conducted by Quality Control Consultants, LLC.
8. Qualifying Inspection Report, Form Q21, dated October 29, 2010, for the manufacturing facility in Wake Forest, North Carolina, conducted by Quality Control Consultants, LLC.
9. Canyon Stone, Inc. 2010 catalog of veneer types and patterns.
10. Report of shear bond tests and mortar strength, RADCO Test Report No. RAD-4866, dated February 22, 2011, for Canyon Stone Inc.